

qualified

on the AC
servicing
the heat-
AC line

110V

Hz

NOTICE !

ponents

made to
shading
replaced


improper

20-EZV(R-C) SCHEMATIC

Sheet 2 of 2

©1982 Nintendo of America Inc.

Revision 1



WARNINGS

1. Service work should only be performed by a service technician.
2. An isolation transformer must be used between supply and the AC plug of the monitor before service or testing is performed since the chassis and ground sink are directly connected to one side of the transformer which could present a shock hazard.
Supply voltage of the video monitor : AC 90V - 50/60Hz
3. X-RAY RADIATION WARNING AND PRODUCT SAFETY NOTICE
This video monitor contains circuits and components included specifically for safety purpose.
For continued protection, no changes should be made to the original design, and components identified by a triangle symbol and by (Δ) on schematic diagram should be replaced with exact factory replacement parts.
DO NOT degrade the safety of the set through servicing.